

Background

UR1 extracted due to lack of coronal tooth tissue available to crown. Root was dehiscence buccally at the apical portion, leaving the extraction socket not having buccal bone intact. Root was extracted, and the implant placed at 6 weeks.



1. Buccal view pre-surgery.



2. Implant in position showing defect.



3. EthOss® placed.



4. Buccal view of healed site at 16 weeks.



5. Healed site at 16 weeks.



6. Exposure showing bone growth over implant no relief to preserve the gingival blood supply.




7. Fit of temporary tooth to allow gingival maturation.



8. Pre-extraction periapical radiograph.



9. Post implant placement periapical radiograph.



10. CT scan of site.